

SPORT
6780

The following maintenance instructions are designed to minimise the cost factor, without compromising the long-term appearance of your floorcovering.

Once the installation is complete, do not traffic for 24 hours until the adhesive has dried and then:



INITIAL CLEAN

- Remove all loose debris and ensure that all traces of dried adhesive are removed from the surface of the floorcovering.
- Mop sweep or vacuum to remove dust and grit.
- Damp mop with a neutral detergent.
- Rinse thoroughly with clean water and remove residue.
- If required, buff with a rotary machine fitted with a clean red pad.



ROUTINE MAINTENANCE

The following recommendations are provided as a guideline, and the frequencies can be changed to optimize the appearance.

DAILY

- It is suggested that maintenance should be carried out at least once a day and if heavily trafficked more frequently.
- Mop sweep or vacuum to remove dust and loose dirt.
- As required, spot clean to remove stubborn marks with an alkaline cleanser. Rinse and remove residue.
- Damp mop entire area.
- As required, buff to restore finish.

WEEKLY/MONTHLY

- Assess the appearance of the floor.
- As required, scrub with a scrubber dryer **fitted only with a red pad**, and using neutral cleanser (pH 7 to 9).
- Rinse thoroughly with clean water and remove residue.
- As required, buff to restore finish.
- Stubborn black marks can be removed by using the centre disc of a scrubbing pad and a small amount of undiluted alkaline cleanser. Place the disc under the sole of the shoe and rub - this gives greater pressure. Rinse the area well with clean warm water and allow to dry.



- The maintenance regime requires the installation of an effective barrier matting system.
- Cleaners and detergents should be diluted as per the manufacturers' instructions. For recommended products, see the Polyflor approved maintenance products sheet.
- Always follow the Health and Safety guidance provided.
- For further guidance, contact Polyflor Customer Technical Support on +44 (0)161 767 1912, or email tech@polyflor.com.
- At the date of issue the data presented is correct. However, Polyflor Ltd. reserve the right to make changes which do not adversely affect performance or quality.

REGULAR CLEANING IS MORE BENEFICIAL TO THE FLOORCOVERING AND MORE COST-EFFECTIVE THAN OCCASIONAL HEAVY CLEANING.

HETEROGENEOUS

POLYFLOR
SPORT

FLOORCARE

POLYFLOR LTD. PO BOX 3 RADCLIFFE NEW ROAD WHITEFIELD MANCHESTER M45 7NR UK
TEL: +44 (0)161 767 1111 UK SALES DIRECT: +44 (0)161 767 1122 UK FAX: +44 (0)161 767 1128
EXPORT FAX: +44 (0)161 767 1166 E-MAIL: INFO@POLYFLOR.COM WWW.POLYFLOR.COM
UK SAMPLE REQUESTS: +44 (0)161 767 2551

James Halcrow
FLOORING



2005

POLYFLORTM
COVERING THE WORLD

October 2009